

## **DTAS ANNUAL CONFERENCE 2018**


# Tanker Specification Review Group update

Aidan Cookson

Compliance Manager, S J Bargh Ltd











- The BS Standard BS3441:1995 has been withdrawn but no replacement standard put in its place.
- Please note that just because a standard has been withdrawn without a replacement, then you are still able to use that standard, as British Standards are a guide to inform best practice, unless informed by legislation, in which case the current standard for the use of will be cited in the current legislation





 The vehicle construction of Use is no longer in place and all vehicles must be built to Whole vehicle Type Approval.








#### **Dairy Code of Practice on Milk Tanker design**















## • Cone filters should be 304 Grade Stainless Steel







 Rear Back Box Working Lights Should Have a Polycarbonate Lens.







• Vent Valve Indicators should show a true indication of the valves position.















## ANY QUESTIONS?

